



H.R.Z. Software Services LTD

MODALIZER+ V 6.1

Release notes

New Features

MPLUS-195 Video capture

MPLUS-205 Deleting a file from the acquisition screen files panel prompts for confirmation

MPLUS-207 JPEG-2000 support

MPLUS-211 JPEG 2000 compression in convert form

MPLUS-212 Image info in image viewer context menu

MPLUS-219 Full screen mode in DICOM Viewer

Bug Fixes

MPLUS-164 modalizer+ crashed when change frame rate on : dicom viewer >>> cine mode (multiple pic)

MPLUS-198 Crash after editing image

MPLUS-215 Fix Trial Activation Form's UI (The final step of the evaluation)

MPLUS-216 TWAIN devices are not detected in MODALIZER+ V6 x64 version

MPLUS-222 Window position of new Modalizer

MPLUS-223 Start Menu icon

MPLUS-224 Fix Number of Images in the local archive for multiframed files

MPLUS-225 x64 installer is missing openjp2.dll



H.R.Z. Software Services LTD

MPLUS-226 64 bit version can't take pictures - crash

MPLUS-228 Hebrew filled in Worklist manager shows gibberish in MODALIZER+

MPLUS-229 Convert multi-frame automatic decodes JPEG frames

MPLUS-230 Make sure to use the slide-bar in ConversionForm when converting to jpeg2000

MPLUS-232 Capture device dropdown in Acquisition screen gets more entries every time you open and close CameraExap

MPLUS-236 Export with local viewer from local archive doesn't add the local viewer